


EXAMPLES OF VINTAGE/AGEING PROBLEMS WITH ACOUSTIC DIAGNOSTIC

Marc Foata

Misaligned Changeover Switch on RT32



Misaligned Changeover Switch on RT32



Arcing Spots

Broken
Changeover
Switch





ABB-UCC wear



Arcing in selector



ABB-UCC wear

